



ITT Rayonier Inc.

Grays Harbor Division. 03
Post Office Box 299
Hoquiam, Washington 98550
(206) 532-1410

February 15, 1983

Mr. George Houck
Industrial Section
Department of Ecology
State of Washington
Olympia, WA 98504

RECEIVED

FEB 16 1983

Dear Mr. Houck:

As per your request, please find enclosed a copy of the report submitted by ITT Rayonier Inc. to EPA Region X advising the agency of the disposition of chrome lignosulfonate at the City of Hoquiam Municipal Landfill.

Also, as requested, find listed the analytical results for hexavalent chrome in both the material deposited and leachate collected from the landfill site. Five individual samples of the deposited material were analyzed.

Sample	ppm Cr (VI) in Extract	% of Oven Dried Material
1	82	0.16
2	145	0.29
3	115	0.23
4	72	0.14
5	78	0.16

Leachate

Filtered 0.06 ppm Cr (VI)
Unfiltered 0.45 ppm Cr (VI)

Leachate sample analyzed for chromium (VI) using the EPA designated method under RCRA (FR 45, 72032 October 30, 1980) Method 8.545.

Sincerely,

ITT RAYONIER INCORPORATED
Grays Harbor Division

Jerry Schaaf

Jerry Schaaf
Environmental Engineer

JKS/lm
Enclosure

USEPA SF



1562891